



## Pro Shop Dilemma: Too many bags—no more space!

### The Challenge

Adding the back 18 holes was a great idea! How to accommodate the number of new member bags during the summer months was another story.

The Golf Club had allocated space to park more carts, but plans did not include expansion of the bag storage area. A new system needed to be found that would hold the extra bags within the existing footprint of the building.



### The Solution

By implementing a MIZER mobile storage system, the capacity of the storage area was increased by 73% and the extra bag issue was solved.

Besides increasing capacity, the new system allowed the clubs to be accessed quickly and efficiently.

18 new holes, additional parking space for carts and a MIZER system to hold the members bags. Growth in membership was now possible without feeling cramped.



Stelterr Factory Direct P.O. Box 5922, Stn.'A', Calgary Alberta, Canada T2H 1Y4  
Tel:403-252-9519 / 1-800-789-5956 Fax:403-252-9515  
Web: [www.stelterr.com](http://www.stelterr.com) Email: [clientservices@stelterr.com](mailto:clientservices@stelterr.com)